



**GENERAL DRAWING NOTES:** U.O.S.

- BREAK ALL CORNERS 0.030 RADIUS OR CHAMFER
- MACHINE ALL FILLETS 0.030 RADIUS
- ALL DIAMETERS CONCENTRIC  $\pm .005$  TIR
- TURNED SURFACE FINISHES 63 RMS OR BETTER
- DRILLED OR BROACHED DETAILS 125 RMS OR BETTER
- DIM AND TOL SHALL BE HELD AFTER PLATING
- STAMP PART & WORK NUMBERS AS SHOWN
- DO NOT USE DRAWING IF MANF. HOLD IS INITIALED

REVISION HISTORY: (MOST CURRENT REV. AT TOP)

REV	DATE	INT.	NOTES
1	12/3/03	MES	REVISION AT MOVE

TOLERANCES: UNLESS OTHERWISE SPECIFIED

- X.XX = +/- 0.010 [X.XX] = +/- [0.05]
- X.XXX = +/- 0.005 [X.X] = +/- [0.1]
- ANGLES = +/- 1.0 DEG. [X] = +/- [0.3]

SCALE: NONE  
MATERIAL: 6061 T-6 ALUM.  
BLACK ANODIZE

**Do Not Scale Drawing**

SCHMITT INDUSTRIES, INC. (SMS)  
2765 NW NICOLAI ST., PORTLAND, OR 97210  
TEL: (503) 227-7908 FAX: (503) 223-1258

PART: AR 4000 SCANNER BASE

NUMBER:	FILE:	SHEET:	
MMP470004	MMP470004.ipt	1 / 1	
DATE:	DRAWN BY:	MANF. HOLD:	HOLD DATE:
12/3/03	MES		